Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: RS-R HARSTAD-157-90- 2029H-1

Field Name: CLEAR WATER Well File #: 18046

Date Incident: 2/29/2016 Time Incident: 13:25 Facility ID Number:

County: MOUNTRAIL Twp: 157 Rng: 90 Sec: 20 Qtr: NW NW

Location Description:

Submitted By: Alberto Yates Received By:

Contact Person: Troy Brunsell

1501 MCKINNEY

HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 500 Feet **Distance Nearest Water Well:** 500 Feet

Type of Incident: Treater Popoff

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No **Units** Recovered Units Spilled **Followup Units** Oil 20 **Barrels** 20 barrels 0 barrels **Brine** Other 0 barrels

Description of Other Released Contaminant:

The Treater popped off spilling approximately 17-20 bbls of oil contained on location. 10 bbls were recovered by a vac truck and disposed at PDI.

Inspected: Written Report Received: 3/14/2016 Clean Up Concluded: 3/8/2016

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

All Impacted material is contained on location.

Potential Environmental Impacts:

There are no potential environmental impacts to the impacted areas offsite. All impacted materials were on site.

Action Taken or Planned:

Dispatched Vacuum Truck to location. 10 bbls were recovered by a vacuum truck and disposed of at PDI. Remaining impacted material will be cleaned up and disposed of to an approved waste facility. RCA investigation will be conducted to determine the factor cause.

Wastes Disposal Location: 10 bbls were recovered by a vacuum truck and disposed of at PDI.

Remaining impacted material will be cleaned up and disposed of to a

HESS approved waste facility.

Agencies Involved:

Updates

Date: 3/1/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC has oversight.